

Inspection Report with SI&A Data

Structure Description: 62.99 Foot - Single Span Concrete Frame (except frame culverts)

2 District: 05 **3 County:** Jefferson **16 Latitude:** 38°14'16.00" **7 Longitude:** 85°39'53.00"

7 Facility Carried: I-64 WB

Milepoint: 0.370

6A Feature Intersected: OLD CANNONS LN

9 Location: WBL .3 MI W-KY 2048 NTRCH

NBI	X
Element	X
Fracture Critical	
Underwater	
Special	

Structure Description: 62.99 Foot - Single Span Concrete Frame (except frame culverts)

NBI CONDITION RATINGS			
58 Deck:	6	61 Channel:	N
59 Superstructure:	7	62 Culvert:	N
60 Substructure:	7	Sufficiency Rating:	98

GEOMETRIC DATA		
48 Max Length Span:		56.102 ft
49 Structure Length:		62.992 ft
32 Approach Roadway:		-3.281 ft
33 Median:		(0) No Median
34 Skew:		28°
35 Flare:		No Flare
50A Curb/Sidewalk Width L:		0.000 ft
50B Curb/Sidewalk Width R:		0.000 ft
47 Horiz. Clearance:		38.386 ft
51 Width Curb to Curb:		-3.281 ft
52 Width Out to Out:		42.671 ft
48 Max Length Span:		56.102 ft

DESIGN	
Substandard:	No
Fracture Critical:	No FC Details
43A Main Span Material:	(1) Concrete
43B Main Span Design:	(07) Frame
45 Number of Spans Main:	1
44A Approach Span Material:	Not Applicable
44B Approach Span Design:	Not Applicable
46 Number of Approach Spans:	0
107 Deck Type:	(1) Concrete-Cast-in-Place
108A Wearing Surface:	(3) Latex Concrete/Similar
108B Membrane:	(0) None
108C Deck Protection:	(0) None
Overlay Y/N:	Yes
Overlay Type:	Latex
Overlay Thickness:	1.250 in
Overlay Date:	2001

ADMINISTRATIVE		
27 Year Built:		1969
106 Year Reconstructed:		0
42A Type of Service On:		(1) Highway
42B Type of Service Under:		(1) Highway
37 Historical Significance:		(5) Not Eligible
21 Maintenance Responsibility:		(01) State Hwy Agency
22 Owner:		(01) State Hwy Agency
101 Parallel Structure:		(L) Left Of II Structure
52 Width Out to Out:		42.671 ft

APPRAISAL	
36A Bridge Railings:	(1) Meets Standards
36B Transitions:	(1) Meets Standards
36C Approach Guardrail:	(1) Meets Standards
36D Approach Guardrail Ends:	(1) Meets Standards
71 Waterway Adequacy:	(N) Not Applicable
72 Approach Alignment:	(8) Equal Desirable Crit
113 Scour Critical:	(N) Not over Waterway
Recommended Scour Critical:	(N) Not over Waterway

CLEARANCES		
10 Vert. Clearance:		99.999 ft
53 Min. Vert. Clearance Over:		99.999 ft
54A Vert. Under Reference:		(H) Hwy beneath struct.
54B Min. Vert. Underclearance:		15.830 ft
55A Lateral Under Reference:		(H) Hwy beneath struct.
55B Min. Lat. Underclearance R:		10.000 ft
56 Min. Lat. Underclearance L:		0.000 ft

LOAD RATINGS	
63 Operating Type:	(1) Load Factor (LF)
64 Operating Rating:	60.0 tons
65 Inventory Type:	(1) Load Factor (LF)
66 Inventory Rating:	36.0 tons
Truck Capacity Type I:	tons
Truck Capacity Type II:	tons
Truck Capacity Type III:	tons
Truck Capacity Type IV:	tons

POSTINGS	
41 Posting Status:	(A) Open, No Restriction
Signs Posted Cardinal:	No
Signs Posted Non-Cardinal:	No
Field Postings Gross:	tons
Field Postings Type I:	tons
Field Postings Type II:	tons
Field Postings Type III:	tons
Field Postings Type IV:	tons

Inspection Report with SI&A Data

38: Re Concrete Slab

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
SQ.FT	2,688	2,615	97%	73	3%	0	0%	0	0%

The 2001 latex overlay has minor cracks and has areas near both ends that are breaking up (40 SF A1, 24 SF A2). There are transverse cracks across the full width of the deck at both of the breakage locations. The asphalt approaches are broken and spalled at both ends.

Soffit copings at both sides of the bridge have some minor deteriorated/spalled areas, some with exposed reinforcement (7 SF south coping, 12 SF north coping). Soffit has rust stains from the chairs/supports for the bottom mat of reinforcement.

510: Wearing Surfaces

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
SQ.FT	2,425	2,094	86%	267	11%	64	3%	0	0%

215: Re Conc Abutment

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
FT	98	86	88%	12	12%	0	0%	0	0%

Minor hairline cracks and small areas of deterioration/spalling in legs/stems of rigid frame (considered as abutments for this element level inspection). Stone facings have some minor deterioration and/or scaling (4 LF at A2, 8 LF at A1).

331: Re Conc Bridge Railing

Units	Total Qty	Qty. St. 1	% in 1	Qty. St. 2	% in 2	Qty. St. 3	% in 3	Qty. St. 4	% in 4
FT	126	96	76%	29	23%	1	1%	0	0%

Barrier wall has minor cracks, most with efflorescence (15 LF North, 14 LF South). There is a large spall on the SW corner (1 LF CS3).

Inspection Report with SI&A Data

STRUCTURE NOTES

-1.25" latex overlay in 2001.
-There is no specific element level condition state assessment of concrete rigid frame bridges. Elements utilized to best describe this rigid frame during this inspection comply with the 2012 BIRM recommendations. TK 4/8/2013

INSPECTION NOTES

Standard inspection performed on 04/15/2015 by L. Boller and A. Porter (DLZ).

WORK

Action: -